



Origin 0,0

U3 & U4 orientation is incorrect C901 has been replaced with a RESISTOR.
 Stand it on end to fit the footprint

Place Wire Link Between U804_6 & U804_8

