

Wire link (underside) between R302 and R303

J1 Pinout Details

- 1 = Sawtooth (output)
- 2 = Linear FM (input)
- 3 = SYNC (input)
- 4 = 0V (power)
- 5 = 0V (power)
- 6 = -9V (reference output)
- 7 = -V_e (power)
- 8 = +V_e (power)
- 9 = +9V (reference output)
- 10 = 0V (power)
- 11 = Logarithmic FM (input)
- 12 = 1V/Octave (input)
- 13 = FINE Tune
- 14 = COARSE Tune

